


# OIL BURNER MOTORS

## Sid Harvey's Vacuum Cleaner Replacement Motors




HP	Replaces	Item#	Reman#
7/8	Sid Harvey models S12, S14, S16 Mastercraft models 641M, 642M, 655M	A166	A166R

## Sid Harvey, A.O. Smith New and Remanufactured Standard Unity Service Factor Oil Burner Motors

### FEATURES:

- Sleeve Bearing.
- Totally enclosed (except shaft end bracket).
- N flange (7-14") and M flange (6-3/4").
- Manual reset.
- 1.0 service factor.



HP	RPM	Amps	Volts	Frame	Lead Length	Lead Position	Reversing	Mfr#	Item	Reman #
1/8	1725	2.5	115	48N	20"	3:00	@ leads	EL2005*	A39-2	A39-2R
1/7	3450	2.5	115	48M			switch	EL2002*■	A39-31	A39-31R
1/7	3450	2.5	115	48M	20"	9:00	CCW	316P951		A39-29R
1/6	1725	3.2	115	48N	20"	3:00	@ leads	XEL2014*	A39-4	A39-4R
1/6	3450	2.7	115	48M	20"	3:00	switch	EL2012	EL2012	
1/4	1725	3.7	115	48N	20"	9:00	@ leads	EL2024	A39-7	
1/4	3450	3.4	115	48N	20"	3:00	switch	EL2022**	A39-42	A39-44R
1/3	3450	5.6	115/230	48N	20"	9:00	switch	GE4788		A39-50R
1/2	3450	6.2/3.1	115/230	48N	10"	10:00	switch	316P955		A39-62R

\*Includes provision for mounting on 4 x 4 conduit box.

\*\*Open shaft end bracket.

- 14" cable at 3:00.

**NOTE:** Remanufactured products available only on exchange for similar defective units. Rotation is designated as viewed from shaft end except where "LE" (lead end) is indicated.