



101-005



101-505

SWING CHECK VALVE • 200 PSI BRASS

Item No.	Size	Connection	Inner Qty.	Master Qty.	Each Wt.
THREADED					
101-001*	1/4"	FPT x FPT	10	100	0.40
101-002*	3/8"	FPT x FPT	10	100	0.40
101-003*	1/2"	FPT x FPT	10	100	0.40
101-004*	3/4"	FPT x FPT	5	60	0.53
101-005*	1"	FPT x FPT	5	40	0.73
101-006*	1-1/4"	FPT x FPT	5	30	1.28
101-007*	1-1/2"	FPT x FPT	4	24	1.70
101-008*	2"	FPT x FPT	2	16	2.62
101-009*	2-1/2"	FPT x FPT	2	8	4.41
101-010*	3"	FPT x FPT	1	6	6.78
101-011*	4"	FPT x FPT	1	3	10.64

- 200 PSI non-shock WOG
- Meets NSF 61 requirements
- Threaded ends comply with ANSI B1.20.1

SOLDER					
101-503*	1/2"	C x C	10	100	0.40
101-504*	3/4"	C x C	5	60	0.55
101-505*	1"	C x C	5	40	0.75
101-506*	1-1/4"	C x C	5	30	1.28
101-507*	1-1/2"	C x C	4	24	1.52
101-508*	2"	C x C	2	16	2.56

- 200 PSI non-shock WOG
- Meets NSF 61 requirements
- Solder ends comply with ANSI B16.18

THREADED – NO LEAD					
101-001NL	1/4"	FPT x FPT	10	100	0.4
101-002NL	3/8"	FPT x FPT	10	100	0.4
101-003NL	1/2"	FPT x FPT	-	15	0.4
101-004NL	3/4"	FPT x FPT	-	15	0.53
101-005NL	1"	FPT x FPT	5	40	0.73
101-006NL	1-1/4"	FPT x FPT	5	30	1.28
101-007NL	1-1/2"	FPT x FPT	4	24	1.7
101-008NL	2"	FPT x FPT	2	16	2.62

- 200 PSI WOA
- Certified to NSF 61-G
- "Lead-Free" Compliant



SOLDER – NO LEAD					
101-503NL	1/2"	C x C	-	20	0.4
101-504NL	3/4"	C x C	-	20	0.55
101-505NL	1"	C x C	5	40	0.75
101-506NL	1-1/4"	C x C	5	30	1.28
101-507NL	1-1/2"	C x C	4	24	1.52
101-508NL	2"	C x C	2	16	2.56

- 200 PSI WOA
- Certified to NSF 61-G
- "Lead-Free" Compliant



* Please call for availability.